

QuickTime™ and a  
decompressor  
are needed to see this picture.

QuickTime™ and a  
decompressor  
are needed to see this picture.



# Casting

2.810

T. Gutowski



# Casting since about 3200 BCE...




Etruscan casting with runners  
circa 500 BCE



China circa 3000BCE

Lost wax jewelry from Greece  
circa 300 BCE

# Bronze age to iron age



Bronze statue of Zeus from Artemision,  
ca. 460 BC

Ancient Greece; bronze  
statue casting circa 450BCE



Iron works in early Europe,  
e.g. cast iron cannons from  
England circa 1543

# Cast Parts

QuickTime™ and a decompressor are needed to see this picture.



QuickTime™ and a decompressor are needed to see this picture.








# Outline

1. **Review:** Sand Casting, Investment Casting, Die Casting
2. **Basics:** Phase Change, Shrinkage, Heat Transfer
3. **Pattern Design**
4. **Environmental Issues**

# Casting

## Readings;

1. *Kalpakjian, Chapters 10, 11, 12*
2. *Boothroyd, "Design for Die Casting"*
3. *Flemings "Heat Flow in Solidification"*
4. *Dalquist "LCA of Casting"*



Note: a good heat transfer reference can be found by  
Profs John Lienhard online <http://web.mit.edu/lienhard/www/ahtt.html>

# Casting Methods



- **Sand Casting**  
High Temperature Alloy,  
Complex Geometry,  
Rough Surface Finish















- **Investment Casting**  
High Temperature Alloy,  
Complex Geometry,  
Moderately Smooth Surface  
Finish



- **Die Casting**  
High Temperature Alloy,  
Moderate Geometry,  
Smooth Surface



# Sand Casting



# Sand Casting

Description: Tempered sand is packed into wood or metal pattern halves, removed from the pattern, and assembled with or without cores, and metal is poured into resultant cavities. Various core materials can be used. Molds are broken to remove castings. Specialized binders now in use can improve tolerances and surface finish.

Metals: Most castable metals.

Size Range: Limitation depends on foundry capabilities. Ounces to many tons.

Tolerances:

Non-Ferrous  $\pm 1/32''$  to  $6''$

Add  $\pm .003''$  to  $3''$ ,  $\pm 3/64''$  from  $3''$  to  $6''$ .

Across parting line add  $\pm .020''$  to  $\pm .090''$  depending on size.

(Assumes metal patterns)

Surface Finish:

Non-Ferrous: 150-350 RMS

Ferrous: 300-700RMS

Minimum Draft Requirements:

$1^\circ$  to  $5^\circ$

Cores:  $1^\circ$  to  $1\ 1/2^\circ$

Normal Minimum Section Thickness:

Non-Ferrous:  $1/8''$  -  $1/4''$


Ferrous:  $1/4''$  -  $3/8''$

Ordering Quantities: All quantities

Normal Lead Time:

Samples: 2-10 weeks

Production 2-4 weeks A.S.A.



# Sand Casting Mold Features




FIGURE 10.7 Schematic illustration of a typical riser-gated casting. Risers serve as reservoirs, supplying molten metal to the casting as it shrinks during solidification. See also Fig. 11.4. *Source:* American Foundrymen's Society.




FIGURE 11.4 Schematic illustration of a sand mold, showing various features.

*Vents*, which are placed in molds to carry off gases produced when the molten metal comes into contact with the sand in the molds and core. They also exhaust air from the mold cavity as the molten metal flows into the mold.

# Videos from Mass & Burlington Foundries



# Production sand casting




FIGURE 11.8

(a) Schematic illustration of a jolt-type mold-making machine. (b) Schematic illustration of a mold-making machine which combines jolting and squeezing.



# Investment Casting

Description: Metal mold makes wax or plastic replica. There are sprued, then surrounded with investment material, baked out, and metal is poured in the resultant cavity. Molds are broken to remove the castings.

Metals: Most castable metals.

Size Range: fraction of an ounce to 150 lbs..

Tolerances:

± .003" to 1/4"

± .004" to 1/2",

± .005" per inch to 3"

± .003" for each additional inch

Surface Finish:

63-125RMS

Minimum Draft Requirements: None

Normal Minimum Section Thickness:

.030" (Small Areas)

.060" (Large Areas)

Ordering Quantities:

Aluminum: usually under 1,000

Other metals: all quantities

Normal Lead Time:

Samples: 5-16 weeks (depending on complexity)

Production 4-12 weeks A.S.A. (depending on subsequent operations).


Talbot Associates Inc.



# Investment Casting

FIGURE 11.18 Schematic illustration of investment casting (lost-wax process). Castings by this method can be made with very fine detail and from a variety of metals. Source: Steel Foundry Society of America.

The **investment-casting process**, also called the *lost-wax process*, was first used during the period 4000-3500 B.C. The pattern is made of wax or a plastic such as polystyrene. The sequences involved in investment casting are shown in Figure 11.18. The pattern is made by injecting molten wax or plastic into a metal die in the shape of the object.



# Die Casting

Description: Molten metal is injected, under pressure, into hardened steel dies, often water cooled. Dies are opened, and castings are ejected.

Metals: Aluminum, Zinc, Magnesium, and limited Brass.

Size Range: Not normally over 2 feet square. Some foundries capable of larger sizes.

Tolerances:

Al and Mg  $\pm .002$ "/in.

Zinc  $\pm .0015$ "/in.

Brass  $\pm .001$ "/in.

Add  $\pm .001$ " to  $\pm .015$ " across parting line depending on size

Surface Finish: 32-63RMS

Minimum Draft Requirements:

Al & Mg:  $1^\circ$  to  $3^\circ$

Zinc:  $1/2^\circ$  to  $2^\circ$

Brass:  $2^\circ$  to  $5^\circ$

Normal Minimum Section Thickness:

Al & Mg: .03" Small Parts: .06" Medium Parts

Zinc: .03" Small Parts: .045" Medium Parts

Brass: .025" Small Parts: .040" Medium Parts


Ordering Quantities:

Usually 2,500 and up.


Normal Lead Time:

Samples: 12-20 weeks

Production: ASAP after approval.




# Die Casting – Cold-Chamber Casting



Cycle in cold-chamber casting: (1) with die closed and ram withdrawn, molten metal is poured into the chamber; (2) ram forces metal to flow into die, maintaining pressure during the cooling and solidification; and (3) ram is withdrawn, die is opened, and part is ejected. Used for higher temperature metals eg Aluminum, Copper and alloys

# Die Casting – Hot-Chamber Casting


Cycle in hot-chamber casting:  
(1) with die closed and plunger withdrawn, molten metal flows into the chamber;  
(2) plunger forces metal in chamber to flow into die, maintaining pressure during cooling and solidification; and  
(3) plunger is withdrawn, die is opened, and solidified part is ejected. Finished part is shown in (4).





# High Melt Temperature

- Reactivity
  - with air, mold mat'ls,
- Gas solubility
  - H<sub>2</sub> gas in Al
- Safety
  - Metal fires, e.g. Mg



# Mold Filling


Bernouli's Equation:

$$h + \frac{p}{\rho g} + \frac{v^2}{2g} = \text{Const.}$$

Reynold's Number:

$$\text{Re} = \frac{vDP}{\mu}$$

- Short filling times
  - Potential Turbulence
- (see Kalpakjian..Ch 10)




# Mold Filling Example

## Mold Filling Example (order of magnitude)

from Bernoulli's Eq'n  
the inlet velocity can  
be estimated as:

$$v \approx \sqrt{2gh}$$

$$= \sqrt{2 \times 10 \frac{\text{m}}{\text{s}^2} \times 10^{-1} \text{m}} = 1.4 \frac{\text{m}}{\text{s}}$$



estimate Reynold's Number




$$Re = \frac{v D \rho}{\mu} = \frac{1.4 \frac{\text{m}}{\text{s}} \cdot 0.5 \text{cm} \cdot 2.7 \frac{\text{g}}{\text{cm}^3}}{10^{-3} \frac{\text{N} \cdot \text{s}}{\text{m}^2}} = 18,900$$

Filling rate: solidification  $< v <$  turbulence, erosion


# Phase Change & Shrinkage

TABLE 10.1



Volumetric Solidification Contraction or Expansion for Various Cast Metals			
Contraction (%)		Expansion (%)	
Aluminum	7.1	Bismuth	3.3
Zinc	6.5	Silicon	2.9
Al-4.5% Cu	6.3	Gray iron	2.5
Gold	5.5		
White iron	4-5.5		
Copper	4.9		
Brass (70-30)	4.5		
Magnesium	4.2		
90% Cu-10% Al	4		
Carbon steels	2.5-4		
Al-12% Si	3.8		
Lead	3.2		



liquid metal



face-centered cubic metal



$$a_{fcc} = 4r/\sqrt{2}$$

$$a_{bcc} = 4r/\sqrt{3}$$

# Solidification of a binary alloy





FIGURE 12.5 (a) Phase diagram for a copper–nickel alloy system and (b) associated cooling curve for a 50%Ni–50%Cu composition during casting.




# Composition change during solidification



**FIGURE 4.5** Phase diagram for nickel–copper alloy system obtained at a slow rate of solidification. Note that pure nickel and pure copper each have one freezing or melting temperature. The top circle on the right depicts the nucleation of crystals. The second circle shows the formation of dendrites (see Section 10.2). The bottom circle shows the solidified alloy, with grain boundaries.

# Pb-Sn phase diagram



**FIGURE 4.7** The lead-tin phase diagram. Note that the composition of the eutectic point for this alloy is 61.9% Sn–38.1% Pb. A composition either lower or higher than this ratio will have a higher liquidus temperature.

# Solidification





FIGURE 10.5 Schematic illustration of three basic types of cast structures:(a) columnar dendritic; (b) equiaxed dendritic; and (c) equiaxed nondendritic. *Source:* D. Apelian.




Dendrite growth in metals- lower surface energy crystallographic planes are favored, producing tree like structures if not disturbed.

# Cast structures



Schematic illustration of three cast structures solidified in a square mold: (a) pure metals; (b) solid solution alloys; and c) structure obtained by using nucleating agents. *Source:* G. W. Form, J. F. Wallace, and A. Cibula

# Properties of castings



e.g. Compare elongation of carbon steels Table 5.3, with cast irons Table 12.3

# How long does it take to solidify?

QuickTime™ and a decompressor are needed to see this picture.

QuickTime™ and a decompressor are needed to see this picture.

Thickness ~ 30 cm

Thickness ~ 0.5 cm




# Heat Transfer – Sand Casting

$$t_s \approx \left( \frac{V}{A} \right)^2$$

**FIGURE 1-6**

Approximate temperature profile in solidification of a pure metal poured at its melting point against a flat, smooth mold wall.




Ref: Mert Flemings "Solidification Processing"

# Thermal Conductivity “k” (W/m·K)

$$q = -k \frac{dT}{dx}$$


Copper	394
Aluminum	222
Iron	29
Sand	0.61
PMMA	0.20
PVC	0.16

# Transient Heat Transfer



$$\rho C_p \frac{\partial T}{\partial t} = k \frac{\partial^2 T}{\partial x^2}$$

$$k \neq k(x)$$



# Sand Casting (see Flemings)


Define new variable

$$\zeta = x / \sqrt{\alpha t}$$

Use

$$\theta = \frac{T - T_M}{T_o - T_M}$$

We seek the transient temperature profile in the sand.



# Sand Casting (see Flemings)

Ordinary differential eq'u

$$\frac{d^2\theta}{d\zeta^2} = -\frac{\zeta}{2} \frac{d\theta}{d\zeta}$$


i.c.  $\theta = 1$  at  $\zeta = \infty$  At  $t=0$ ,  $T=T_o$  everywhere

b.c.  $\theta = 0$  at  $\zeta = 0$  At  $x=0$ ,  $T=T_m$  always

This will allow us to calculate the heat lost by the metal at the boundary with the sand tooling

$$\theta = \text{erf}\left(-\frac{\zeta}{2}\right)$$

# Solidification Time



Heat required to solidify to distance "s"

$$= A \cdot s \cdot \rho \cdot H$$

Rate eq'n (per unit area)

$$\rho H \frac{ds}{dt} = -\dot{q} = k \left( \frac{\partial T}{\partial x} \right)_{x=0}$$

**Use Flemings result here**



# Solidification Time (cont.)

this leads to

$$s = \frac{2}{\sqrt{\pi}} \left( \frac{T_M - T_O}{\rho_M H_M} \right) \sqrt{K_s \rho_s C_{p_s} t}$$

$$\text{let } s = \frac{V}{A}$$

$$t = C \left( \frac{V}{A} \right)^2$$

Chvorinov's rule


The constant C is determined by experiment.

Several references suggest that values range:

$C \sim 2$  to  $4 \text{ min/cm}^2$  (with most data for iron and steel)

# Solidification Time; thin slab

$$t_{cool} = f\left(\frac{V}{A}\right)$$



$$\frac{V}{A} = \frac{L \times h \times w}{2 \times L \times w} = \frac{h}{2}$$

# How long does it take to solidify?

Order of magnitude estimate using half thickness, &  $C = 3.3 \text{ min/cm}^2$

QuickTime™ and a decompressor are needed to see this picture.


QuickTime™ and a decompressor are needed to see this picture.

Thickness ~ 30 cm  
Solidification time =  $3.3 (30/2)^2 \text{ [min]} \sim 12 \text{ hrs}$

Thickness ~ 0.5 cm  
 $t = 3.3 (0.5/2)^2 \text{ [min]} \sim 12 \text{ sec}$

# What happened?

---



# Pattern Design suggestions




Figure 7.2.24 Identifying hot spots in castings by using outward projecting arrows of length half the casting thickness. Where arrows overlap, hot spots may develop. (Courtesy of Meehanite Metal Corp.)




Figure 7.2.25 Examples of relative cooling times. (Courtesy of Meehanite Metal Corp.)




Figure 7.2.26 Fillet all sharp angles. (Courtesy of Meehanite Metal Corp.)

# More Pattern Design suggestions




Figure 7.2.28 Avoid abrupt section changes. (Courtesy of Meehanite Metal Corp.)




Figure 7.2.29 Design for uniform thickness in sections. (Courtesy of Meehanite Metal Corp.)





Figure 7.2.30 More intersection details. (Courtesy of Meehanite Metal Corp.)




Figure 7.2.31 Design for bolting or bearing bosses. (Courtesy of Meehanite Metal Corp.)



# And more...





**Figure 7.2.32**  
Omit outside bosses and the need for cores.  
(Courtesy of Meehanite Metal Corp.)



**Figure 7.2.35**  
Avoid using ribs which meet at acute angles.  
(Courtesy of Meehanite Metal Corp.)

# Heat Transfer – Die Casting

$$t_s \approx \left( \frac{V}{A} \right)^1$$



**FIGURE 1-9**  
Temperature profile during solidification against a large flat mold wall with mold-metal interface resistance controlling.

# Film Coefficients “ $h$ ” W/m<sup>2</sup>·K


$$q = -hA(\Delta T)$$

	Carbon coating	high pressure	low pressure	polished die
Typical die casting				
Natural convection				
Flowing air				

The diagram shows three arrows pointing from the labels 'Carbon coating', 'high pressure', and 'low pressure' to the range '1,000 - 10,000' in the table. The arrow for 'high pressure' is red, while the others are black.


# Die casting contact resistance

Also see Boothroyd Ch 10, p446-447



# Die Casting Solidification Time

Time to form  
solid part



$$\dot{q} = -\bar{h}A(T_M - T_o) = \rho_M H_M A \frac{ds}{dt}$$

$$t = \frac{\rho_M H_M V}{\bar{h}(T_M - T_o) A}$$

Also need to cool casting to below  $T_M$

to eject  $\rightarrow T_{\text{eject}}$

and will inject at  $T_{\text{inject}} > T_M$ .

Time to cool part to the ejection temperature. (lumped parameter model)

$$mC_p \frac{dT}{dt} = -Ah (T - T_o) \quad \text{Let,} \quad \theta = T - T_o$$

$$\int_{\theta_i}^{\theta_f} \left( \frac{d\theta}{\theta} \right) = -\frac{Ah}{mC_p} \int_{t_i}^{t_f} dt$$

Integration yields...

$$t = \frac{-mC_p}{Ah} \ln \frac{\Delta\theta_f}{\Delta\theta_i}$$



# Time to cool part to the ejection temperature. (lumped parameter model)

For thin sheets of thickness “w”, including phase change

$$\Delta\theta_i = T_i + \Delta T_{sp} - T_{mold}$$

$$\Delta T_{sp} = H/C_p$$

$$\Delta\theta_f = T_{eject} - T_{mold}$$

$$t = \frac{w \rho C_p}{2h} \ln \left( \frac{T_{inject} + \Delta T_{sp} - T_{mold}}{T_{eject} - T_{mold}} \right)$$

“sp” means superheat

Approximations,

$$t \approx 0.42 \text{ sec/mm} \times w_{max} \text{ (Zn)}$$

$$t \approx 0.47 \text{ sec/mm} \times w_{max} \text{ (Al)}$$


$$t \approx 0.63 \text{ sec/mm} \times w_{max} \text{ (Cu)}$$

$$t \approx 0.31 \text{ sec/mm} \times w_{max} \text{ (Mg)}$$

Ref Boothroyd, Dewhurst, Knight p 447

# Pattern Design Issues (Alum)

- Shrinkage Allowance  $.013/1$
- Machining Allowance  $1/16''$
- Minimum thickness  $3/16''$
- Parting Line
- Draft Angle  $3$  to  $5\%$
- Uniform Thickness



# Pattern Design

Table 12.1

## Normal Shrinkage Allowance for Some Metals Cast in Sand Molds

Metal	Percent
Gray cast iron	0.83 – 1.3
White cast iron	2.1
Malleable cast iron	0.78 – 1.0
Aluminum alloys	1.3
Magnesium alloys	1.3
Yellow brass	1.3 – 1.6
Phosphor bronze	1.0 – 1.6
Aluminum bronze	2.1
High-manganese steel	2.6







FIGURE 12.5 Redesign of a casting by making the parting line straight to avoid defects. Source: *Steel Casting Handbook*, 5th ed. Steel Founders' Society of America, 1980. Used with permission.




FIGURE 11.7 Taper on patterns for ease of removal from the sand mold.



# Pattern materials




# Digital Sand Casting




# Extra slides

1. Solidification behavior (Pop Quiz)
2. Steady state conduction through composite walls
3. Environmental issues for sand casting

Pop quiz; If you top fill the mold below, what will the part look like after solidification?




Can you explain these features?





# Steady State Conduction Heat Transfer

Figure 1




$$q = -k \frac{T_1 - T_2}{\Delta x}$$

Fourier's Law

# Steady State Conduction Heat Transfer

Figure 2



In steady-state  $q_A = q_B = q_C = q_D = q$ ,

hence for each layer  
(large  $\Delta T_i$  implies a large  $\Delta R_i$  and vice versa)

$$\frac{\Delta T_i}{R_i} = q = \text{constant}$$

Since  $\Delta T = \sum \Delta T_i \Rightarrow$  Equivalent  $R_{eq} = \sum R_i$


i.e.  $q = \Delta T / R_{eq}$ .

Hence, referring to Fig. 2  $R_{eq} \approx R_c \Rightarrow q \approx \frac{\Delta T}{R_c}$ .

i.e. heat transfer is controlled by layer "c" with the highest thermal resistance  $R_c$

# Sand casting; Environmental Issues

- Energy
- Emissions
- Sand
- Waste water




input  
 vapor waste  
 aqueous waste  
 solid waste

included in analysis

not included in analysis

# Cast Iron Example (Cupola)

Stage	MJ/kg
Mold preparation	3.0
Metal preparation	6.7
Casting	0.7
Finishing	1.2
<b>Total at foundry</b>	<b>11.6</b>
Electricity losses	0.0
<b>TOTAL</b>	<b>~12 MJ/kg</b>



# Melting Energy

- pour : part size Ratio ~ 1.1 to 3

- thermal energy


$$\Delta H = mC_p\Delta T + m\Delta H_f \Rightarrow 0.95 \text{ (aluminum)}, 1.3 \text{ MJ/kg (cast iron)}$$

- melting and holding efficiency,

- *Losses at the utilities for electric furnaces*

- National statistics (*including elect losses*)

*13 – 17 MJ/kg (total)*




# Improving sand casting

$$\eta = \frac{C_p \Delta T + \Delta h}{15 \frac{MJ}{kg}} \cong \frac{1}{15} \cong 7\%$$


- reduce runners, risers
- improve furnace efficiency
- use waste heat
- use fuel Vs electricity

# Process Material Flow



# Metals & sand used in Casting


- Iron accounts for 3/4 of US sand cast metals
  - Similar distribution in the UK
  - Share of aluminum expected to increase with lightweighting of automotive parts
- Sand used to castings out– about 5.5:1 by mass
- Sand lost about 0.5:1 in US; 0.25:1 in UK





# Aggregate TRI data (toxic releases)

kg released per tonne cast



# Sandcasting Emissions Factors

- Emissions factors are useful because it is often too time consuming or expensive to monitor emissions from individual sources.
- They are often the only way to estimate emissions if you do not have test data.
- However, they can not account for variations in processing conditions

<b>Iron Melting Furnace Emissions Factors (kg/Mg of iron produced)</b>				
<b>Process</b>	<b>Total Particulate</b>	<b>CO</b>	<b>SO<sub>2</sub></b>	<b>Lead</b>
Cupola				
Uncontrolled	6.9	73	0.6S*	0.05- 0.6
Baghouse	0.3			
Electric Induction				
Uncontrolled	0.5	-	-	0.005 - 0.07
Baghouse	0.1			
*S= % of sulfur in the coke. Assumes 30% conversion of sulfur into SO <sub>2</sub> .				
Source: EPA AP-42 Series 12.10 Iron Foundries <a href="http://www.epa.gov/ttn/chief/ap42/ch12/bgdocs/b12s10.pdf">http://www.epa.gov/ttn/chief/ap42/ch12/bgdocs/b12s10.pdf</a>				

<b>Pouring, Cooling Shakeout Organic HAP Emissions Factors for Cored Greensand Molds (lbs/ton of iron produced)</b>	
<b>Core Loading</b>	<b>Emissions Factor</b>
AFS heavily cored	0.643
AFS average core	0.5424
EPA average core	0.285
Source: AFS Organic HAP Emissions Factors for Iron Foundries <a href="http://www.afsinc.org/pdfs/OrganicHAPemissionfactors.pdf">www.afsinc.org/pdfs/OrganicHAPemissionfactors.pdf</a>	

# TRI Emissions Data – 2003

XYZ Foundry (270,000 tons poured)

Chemical	Total Air Emissions (lbs)	Surface Water Discharge (lbs)	Total on-site Release (lbs)	Total transfers off site for waste Management (lbs)	Total waste Managed (lbs)
COPPER	69	9	78	74,701	74,778
DIISOCYANATES	0	0	0	20	20
LEAD	127	40	167	39,525	39,692
MANGANESE	274	48	322	768,387	768,709
MERCURY	14.35	0	14.35	0.25	14.6
PHENOL	6,640	5	6,645	835	7,484
ZINC (FUME OR DUST)	74	0	74	262,117	262,191
<b>TOTALS</b>			<b>7,300</b>	<b>1,145,585</b>	<b>1,152,889</b>

# Input Metals for Casting

