

# Control of Manufacturing Processes

David Hardt

October 30, 2013



**Laboratory for Manufacturing  
and Productivity**

# Topics for Today

- Physical Origins of Variation
  - Process Sensitivities
- Statistical Models and Interpretation
  - Process as a Random Variable(s)
  - Diagnosis of Problems
- Shewhart Charts
- Process Capability
- Next Steps: Optimization and Control

# Process Objectives?

- Rate
- Quality
- Cost
- Flexibility




# Process Control Objectives?

- Rate
- **Quality**
  - **Conformance to Specifications wrt**
    - **Geometry**
    - **Properties**
- Cost
- Flexibility



# Lab Processes



## CNC Turning

Critical Dimension:

Shaft Diameter

# Lab Processes

## Brake Bending

Critical Dimension:



Part Angle



# Lab Processes

## Injection Molding

Critical Dimension:




# Lab Processes



## Thermofforming

Critical Dimension:



# Other Related Problems: Cost, Rate and Flexibility:

---

- 100% inspection with high scrap rates
  - low throughput
  - high costs
- 100% Inspection with frequent rework
  - low throughput
  - high costs
- High Variability at changeover
  - Reluctance to changeover
  - low flexibility




# Manufacturing Processes



- How are they defined?
- How to they do their thing?
- How can they be categorized?
- **Why don't they always get it right?**

# Origins of Variation



# The Process Components



- |   |   |  |   |   |
|---|---|--|---|---|
| <ul style="list-style-type: none"><li>• Etch bath</li><li>• Injection Molder</li><li>• Lathe</li><li>• Draw Press</li><li>• ...</li></ul> |  | <ul style="list-style-type: none"><li>• Coated Silicon</li><li>• Plastic Pellets</li><li>• Bar stock</li><li>• Sheet Metal</li><li>• ...</li></ul> |  | <ul style="list-style-type: none"><li>• Semiconductor</li><li>• Connector Body</li><li>• Shaft</li><li>• Hood</li><li>• ...</li></ul> |
|---|---|--|---|---|



# What Causes *Variation* in the Process Output?

- Material Variations
  - Properties, Initial Geometry
- Equipment Variations
  - Non-repeatable, long term wear, deflections
- Operator Variations
  - Inconsistent control, excessive “tweaking”
- “Environment” Variations
  - Temperature and Handling inconsistencies

# Can We Rank These?

- Likelihood of Variation?
- Frequency of Variation?
- Magnitude of Variation?
- Sensitivity to Variation?

# Can We Rank These?

- Equipment
  - Fixed “Iron”
  - Can be Automated (Controlled) to Keep Energy States as Desired
- Material
  - “Flows” Through the Process
    - Constantly Changing
  - Energy Transfer from Equipment Variable

# Process Control Hierarchy

- **Identify and Reduce Disturbances**
  - Good Housekeeping (Ops Management)
  - Standard Operations (SOP' s)
  - **Statistical Analysis and Identification of Sources**
  - **Feedback Control of Machines**
  - **Reduce Sensitivity** (Process Optimization or Robustness)
    - **Measure Sensitivities via Designed Experiments**
    - Adjust “free” parameters to minimize
- **Measure output and manipulate inputs**
  - **Feedback control of Output(s)**

# Why not Always “Process Output Control”?

- Lack of Measurements
  - Shape not accessible
- Lack of Spatial Resolution
  - Complex shape, simple control  $u$
- Cost/Benefit vs. Other Methods
- Sufficiency of Equipment Control
  - e.g. numerical control

# Modeling Variation



# Applying Statistics to Manufacturing: The Shewhart Approach (circa 1925)\*

- All Physical Processes Have a Degree of Natural Randomness
- A Manufacturing Process is a Random Process if all “Assignable Causes” (identifiable disturbances) are eliminated
- A Process is “In Statistical Control” if only “Common Causes” (Purely Random Effects) are present.

W.A. Shewhart, “The Applications of Statistics as an Aid in Maintaining Quality of a Manufactured Product”, Journal of the American Statistical Association, 20, No.. 152, Dec. 1925.

# Shewhart Applied to Manufacturing


- Measure and Plot the Process Output
- Look for Any Sign of Non-Random (Deterministic) Behavior
  - Out of Statistical Control
- Identify the Cause of that Behavior and Reduce or Eliminate it
- Verify That the Process is Now Purely Random
  - In Statistical Control



# Statistical Models for Manufacturing




# Consider: Turning Process



# Observations from Experiments


- Randomness + Deterministic Changes




random or  
unknown

$\Delta\alpha$

# Brake Bending of Sheet




# Bending Process



# Observations from Bending Process

- Clear Input-Output Effects (Deterministic)
- Also Randomness as well





Angle  
changes  
with depth

$\Delta Y \rightarrow \Delta u$


# Observations from Injection Molding

Run Chart for Injection Molded Part




# Consider: No Effective Changes ( $\partial Y/\partial u=0$ )

- Injection Molding Entire Run






# Injection Molding (S' 2003)




# How To Model to Distinguish these Effects?



A Random Process + A Deterministic Process

# Random Processes

- Consider the Output-only, “Black Box” view of the Run Chart



- How do We Characterize The Process?
  - Using  $Y(t)$  only
- WHY do we Characterize the Process
  - Using  $Y(t)$  only?

# How to Describe Randomness?

- Look at a **Frequency Histogram** of the Data
- Estimates likelihood of certain ranges occurring:

- $\Pr(y_1 < Y < y_2)$



- “Probability that a random variable  $Y$  falls between the limits  $y_1$  and  $y_2$ ”

# Analysis of Histograms


- Is there a consistent pattern?
- Is an underlying “parent” distribution suggested?

# Process Outputs as a Random Variable

- The Histogram suggests a *pdf*
  - Parent or underlying behavior “sampled” by the process
- Standard Forms (There are many)
  - e.g. The Uniform and Normal pdf’ s




# Histogram for CNC Turning




# Histogram for Bending

(MIT 2002 data)



0.3 in depth only






# Histogram for Bending

(MIT 2002 data)

0.6 in depth only



# Conclusion?

- When there are no input effect (no  $\Delta u$  or  $\partial Y/\partial u$ ) a consistent histogram pattern *can* emerge
- How do we use knowledge of this pattern?
  - Predict behavior
  - Set limits on “normal” behavior
- *Define analytical probability density functions*


# Underlying or “Parent” Probability

- A model of the “true”, continuous behavior of the random process
- Can be thought of as a continuous random variable obeying a set of rules (the *probability function*)
- We can only glimpse into these rules by sampling the random variable (i.e. the process output)
- Underlying process can have
  - Continuous Values (e.g. geometry)
  - Discrete Values (e.g. defect occurrence)

# The Uniform Distribution

$$p(x) = \frac{1}{r} \quad \text{for } x_1 < x < x_2$$


$$p(x) = 0 \quad \text{for } x < x_1 \quad \text{or} \quad x > x_2$$



# Standard Normal Distribution


Normal Probability Density Function for  $s^2 = 1, m=0$

$$p(x) = \frac{1}{s\sqrt{2\pi}} e^{-\frac{1}{2} \left(\frac{x-m}{s}\right)^2}$$



# Continuous Distribution: Normal or Gaussian


cdf



pdf

$$x \sim N(\mu, \sigma^2)$$


$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} e^{-\frac{1}{2}\left(\frac{x-\mu}{\sigma}\right)^2}$$



# Properties of the Normal pdf

- Symmetric about mean
- Only two parameters:


$\mu$  and  $\sigma^2$

$$p(x) = \frac{1}{s\sqrt{2\pi}} e^{-\frac{1}{2} \left(\frac{x - \mu}{s}\right)^2}$$


- Superposition Applies:
  - sum of normal random variables has a normal distribution

# Interpretation of the PDF: Confidence Intervals

- Probability that  $|x| > \mu + 3\sigma = 3/1000$





# Model Calibration

- For the Normal PDF, we need two parameters:  $\mu$  *and*  $\sigma$
- We have to **estimate**  $\mu$  *and*  $\sigma$  using sample statistic based on samples of the output (i.e. measurements)

# Sample Statistics

$x(j)$  = samples of  $x(t)$  taken  $n$  times

$$\bar{x} = \frac{1}{n} \mathop{\text{a}}\limits_{j=1}^n x(j) : \text{Average or Sample Mean}$$


$$S^2 = \frac{1}{n-1} \mathop{\text{a}}\limits_{j=1}^n (x(j) - \bar{x})^2 : \text{Sample Variance}$$

$$S = \sqrt{\frac{1}{n-1} \mathop{\text{a}}\limits_{j=1}^n (x(j) - \bar{x})^2} : \text{Sample Std.Dev.}$$


# Conclusions

- All Physical Processes Have a Degree of **Natural Randomness**
- We can Model this Behavior using **Probability Distribution Functions**
- We can **Calibrate** and Evaluate the Quality of this Model from Measurement Data using appropriate **Sample Statistics**


# In-Control (Almost)




# Not In-Control



# “Not In-Control”




# “In-Control”




The Parent Distribution  
**Does Not** Change with  
Time

# “Not In-Control”





# “Not In-Control”




# Applying in Real-Time: Xbar and S Charts


- Shewhart:
  - Plot *sequential average* of process
    - Xbar chart
    - Distribution?
  - Plot sequential sample standard deviation
    - S chart

# Data Sampling and Sequential Averages

- Given a sequence of process outputs



# Data Sampling




$n$  measurements  
at sample  $j$

$$\bar{x}_j = \frac{1}{n} \sum_{i=(j-1)\Delta T + 1}^{j\Delta T + n} x_i \quad \text{sample } j \text{ mean}$$


$$S_j^2 = \frac{1}{n-1} \sum_{i=(j-1)\Delta T}^{j\Delta T + n} (x_i - \bar{x}_j)^2 \quad \text{sample } j \text{ variance}$$

# ● Plot of $\bar{x}$ and $S$ Random Data $n=5$



$\bar{x}$



$S$



# Overall Statistics



# Setting Chart Limits

- Expected Ranges
- Confidence Intervals
  - Intervals of  $\pm n$  Standard Deviations
  - Most Typical is  $\pm 3\sigma$

# Chart Limits - Xbar

- If we knew  $\sigma_x$  then:

$$S_{\bar{x}} = \sqrt{\frac{1}{n}} S_x$$

- But Since we *Estimate* the Sample Standard Deviation, then

$$E(S_j) = C_4 S_{\bar{x}} \quad (S_j \text{ is a biased estimator})$$

$$\text{where } C_4 = \frac{\sqrt{2}}{\sqrt{\pi}} \frac{\Gamma(n/2)}{\Gamma((n-1)/2)}$$



# Chart Limits xbar chart

The estimate of *True Sample Mean Variance* (variance of the mean) is biased

To remove this bias for the  $\bar{x} \pm 3\sigma$  limits we use:

$$UCL = \bar{\bar{x}} + 3 \frac{\bar{S}}{C_4 \sqrt{n}} \quad LCL = \bar{\bar{x}} - 3 \frac{\bar{S}}{C_4 \sqrt{n}}$$

For the example  $n=5$

$$C_4 = (0.5)^{1/2} \frac{G(2.5)}{G(2)} = 0.707 \frac{1.33}{1} = 0.94$$

# Chart Limits S

The variance of the estimate of S can be shown to be:


$$S_S = S\sqrt{1 - C_4^2}$$

So we get the chart limits:


$$UCL = \bar{S} + 3\frac{\bar{S}}{C_4}\sqrt{1 - C_4^2}$$

$$LCL = \bar{S} - 3\frac{\bar{S}}{C_4}\sqrt{1 - C_4^2}$$

# Example xbar



# Example S



# Detecting Problems from Running Data

- Appearance of data
  - Confidence Intervals
  - Frequency of extremes
  - Trends

# Western Electric Rules

- Points outside limits
- 2-3 consecutive points outside 2 sigma
- Four of five consecutive points beyond 1 sigma
- Run of 8 consecutive points on one side of center

# Test for “Out of Control”

- Extreme Points
  - Outside  $\pm 3\sigma$
- Improbable Points
  - 2 of 3  $> \pm 2\sigma$
  - 4 of 5  $> \pm 1\sigma$
  - All points inside  $\pm 1\sigma$

# Tests for “Out of Control”


- Consistently above or below centerline
  - Runs of 8 or more
- Linear Trends
  - 6 or more points in consistent direction
- Bi-Modal Data
  - 8 successive points outside  $\pm 1\sigma$



# Applying Shewhart Charting

- Find a run of 25-50 points that are “in-control”
- Compute chart centerlines and limits
- Begin Plotting subsequent  $\bar{x}_j$  and  $S_j$
- Apply rules, or look for trends, improbable events or extremes.
- If these occur, process is “out of control”


# Real-Time



# Out of Control


- Data is not Stationary  
( $\mu$  or  $\sigma$  are not constant)
- Process Output is being “caused” by a disturbance (common cause)
- This disturbance can be identified and eliminated
  - Trends indicate certain types
  - Correlation with know events
    - shift changes
    - material changes

# “In-Control”



What will chart  
look like?

# “Not In-Control”




# Another Use of the Statistical Process Model:

## The Manufacturing -Design Interface

- We now have an empirical model of the process

How “good” is the process?

Is it capable of producing what we need?




# Process Capability

- Assume Process is In-control
- Described fully by  $\bar{x}$  and  $s$
- Compare to Design Specifications
  - Tolerances
  - Quality Loss

# Design Specifications

- **Tolerances: Upper and Lower Limits**






# Design Specifications


- **Quality Loss:** Penalty for Any Deviation from Target

$$QLF = L^*(x-x^*)^2$$



# Use of Tolerances: Process Capability

- Define Process using a Normal Distribution
- Superimpose  $x^*$ , LSL and USL
- Evaluate Expected Performance



# Process Capability

- Definitions

$$C_p = \frac{(USL - LSL)}{6S} = \frac{\text{tolerance range}}{99.97\% \text{ confidence range}}$$

- Compares ranges only
- No effect of a mean shift:


# Process Capability: $C_{pk}$

$$C_{pk} = \min \left\{ \frac{(USL - m)}{3S}, \frac{(m - LSL)}{3S} \right\}$$


= Minimum of the normalized deviation from the mean

- Compares effect of offsets


$$C_p = 1; C_{pk} = 1$$




$$C_p = 1; C_{pk} = 0$$



$$C_p = 2; C_{pk} = 1$$



$$C_p = 2; C_{pk} = 2$$





# Effect of Changes

- In Design Specs
  - In Process Mean
  - In Process Variance
- 
- What are good values of  $C_p$  and  $C_{pk}$ ?

# Cpk Table


Cpk	z	P < LS or P > USL
1	3	1E-03
1.33	5	3E-07
1.67	4	3E-05
2	6	1E-09

# The “6 Sigma” problem

$$P(x > 6\sigma) = 18.8 \times 10^{-10}$$

$$C_p = 2$$

$$C_{pk} = 2$$




# The 6 $\sigma$ problem: Mean Shifts

$$P(x > 4\sigma) = 31.6 \times 10^{-6}$$

$$C_p = 2$$


$$C_{pk} = 4/3$$

Even with a mean shift of  $2\sigma$   
we have only 32 ppm out of  
spec



# Capability from the Quality Loss Function

$$QLF = L(x) = k^*(x-x^*)^2$$



Given  $L(x)$  and  $p(x)$  what is  $E\{L(x)\}$ ?

# Expected Quality Loss

$$\begin{aligned} E\{L(x)\} &= E\left[k(x - x^*)^2\right] \\ &= k\left[E(x^2) - 2E(xx^*) + E(x^*{}^2)\right] \\ &= kS_x^2 + k(m_x - x^*)^2 \end{aligned}$$

Penalizes  
Variation

Penalizes  
Deviation

# Process Capability

- The reality (the process statistics)
- The requirements (the design specs)
- $C_p$  - a measure of variance vs. tolerance
- $C_{pk}$  a measure of variance from target
- Expected Loss- An overall measure of goodness


# Process Control Hierarchy

- Identify and Reduce Causal Disturbances
  - Good Housekeeping
  - *Standard Operations (SOP's)*
  - *Feedback Control of Machines*
    - ***Eliminate Equipment Variations***
  - Statistical Analysis and Identification of Sources (SPC)
    - ***Eliminate Assignable Causes***





# Process Control Hierarchy

- NEXT: Reduce Sensitivity to Disturbance
  - Measure Sensitivities via Designed Experiments (DOE)
  - Adjust “free” parameters to minimize variations




# Example: Bending Sensitivity to Yield Stress

Simple Example: Die Width for Air Bending (An adjustable equipment property):



- Wide Die:
  - Low force,
  - high spring back<sub>1</sub>,
  - high sensitivity to variations in yield stress
- Narrow Die:
  - High force,
  - Higher material stress,
  - Lower spring back<sub>1</sub>,
  - Lower sensitivity to variations in yield stress,

# Final Step : “Output Control”



## Examples:


- Web Thickness in Milling
- Sheet Thickness in Rolling
- Sheet Angle in Bending

# Implementing Product Feedback Control


- Continuous In-Process Measurements
  - Regulate Process States In-Process
- Sampling and Monitoring (SPC)
  - Measure After-Process and Diagnose
- **Part to Part Sampling and Control**
  - Cycle to Cycle Control: Measure After each Cycle and Improve Process Capability

# Conclusions: Single Variable Case

- Cycle to Cycle Control
  - Obeys Root Locus Prediction wrt Dynamics
  - Amplifies White Noise Disturbance  
Attenuates Colored Noise Disturbance
  - Can Reduce Mean Error (Zero if I-control)
  - Can Reduce “Open Loop” Expected Loss




# Feedback Control Objectives





# It Works!:

## Bending Step Disturbance


- Effect of Material Change
  - Switch to a Stiffer Material – more springback.



# Manufacturing Objective



Design Goal



- Method?:
  - SPC
  - Optimization
  - Output Feedback



# Conclusions

- Shewhart Charts
  - Application of Statistics to Production
  - Plot Evolution of Sample Statistics  $\bar{x}$  and  $S$
  - Look for Deviations from Model
- Process Capability
  - A measure of the process to meet a requirement
  - Includes variance and bias
  - Gets design and manufacturing talking
- If That's Not Good Enough
  - DOE/Optimization
  - Feedback Control
  - ...