


# *Machining Part 2*

- Production Machining
  - Systems overview
  - Process Planning
  - Design for Machining
- New Developments
- Environmental Issues



# *Production Machining*



dimensions  
features  
tolerances  
material properties  
hardness  
surface finish

machines  
tools  
fixtures  
operations  
inspection  
sequence

machines  
arrangement  
materials handling  
inspection/Q.C.  
operator's/skill level

# *How to proceed...*

- Know options available: machines, tools, systems etc.
- Know how to connect the dots
  - part drawing to process plans
    - ex. tight tolerances → extra operations (DFM)
  - process plans for systems
    - ex. multiple steps need to be balanced to have smooth flow


# *Picking Manufacturing Systems*

- **Job Shops** – very flexible, low volumes, high variety
- **Flow shops** – arrange dedicated equipment in order of operations, balance flow, deskill jobs
- **Transfer Lines** – automated, hardwired flow shop
- **Flexible Mfg. Systems (FMS)** – automate transfer between machines, allow skipping and double back
- **Toyota cell** – special arrangement of flow shop with many machines per operator






# Flow Shop - dedicated





# Transfer line - hardwired




# Flexible Manufacturing System (FMS)


Figure 1 AlliedSignal's flexible manufacturing system



# Toyota Mfg Cell



# Machining Systems Classification



Ref J T. Black







# Process planning

How would you machine this part?





Figure A1: Rod support



Assumption:

1. We begin with a stock size of 2.5" X 2.25" X 12"
2. This will be manufactured in a job shop for very low quantity

We will use:

- A bandsaw to roughly cut the stock to size
- A manual vertical mill to create the planar features and the holes
- A belt sander to sand the radii ( assuming the tolerance is not very high)

# Machines, tools, fixture



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
Belt sander	Bore 1" radius
	Sand 0.5 radii






Figure A1: Rod support



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
Belt sander	Sand 0.5 radii






Figure A1: Rod support



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	<b>Mill width to 2"</b>
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
Belt sander	Sand 0.5 radii





Figure A1: Rod support



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	<b>Mill out 2"X1.5"X4"</b>
	Drill hole 1" diameter
	Bore 1" radius
Belt sender	Sand 0.5 radii





Figure A1: Rod support



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
Belt sander	Sand 0.5 radii






Figure A1: Rod support

\*





Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
	<b>Bore 1" radius</b>
Belt sender	Sand 0.5 radii






Figure A1: Rod support

\*





Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
Belt sander	Sand 0.5 radii















Figure A1: Rod support





# Process |



Machine	Operation
Horizontal band saw	Saw stock to ~4.125"
Manual vertical mill	Mill two ends to length 4"
	Mill width to 2"
	Mill out 2"X1.5"X4"
	Drill hole 1" diameter
	Bore 1" radius
Belt sander	Sand 0.5 radii

# Simplified Time Estimation Booklet for Basic Machining Operations

K. C. Polgar, T. G. Gutowski, G. W. Wentworth

## Table of Contents:

<b>Page#</b>	<b>Topic</b>
3.	<b>TIME ESTIMATION TABLES</b>
4.	7" x 12" Wet Horizontal / Vertical Bandsaw
6.	Cold Saw
7.	Manual Vertical Mill
10.	CNC 3-Axis Vertical Mill
12.	Manual Horizontal Mill
14.	Manual Turret Lathe
17.	CNC Turret Lathe
18.	Drill Press
22.	CNC 3-Axis Surface Grinder
23.	Belt Sanding
24.	Inspection
25.	<b>APPENDIX A: HOW TO USE THIS BOOKLET</b>
25.	The process plan
27.	Estimating the time
31.	Comparisons
33.	<b>APPENDIX B: OTHER USEFUL TABLES</b>
34.	B.1 Surface finish requirements for various design applications
35.	B.2 Tolerance and surface roughness for various manufacturing processes
36.	B.3 Process tolerances
37.	B.4 Standard material shapes and sizes
38.	B.5 Material densities and costs

# Appendix **A**

## How to Use this Booklet

The following is a step-by-step example of a time estimate. It will illustrate the various steps involved and help explain the different sections of the time estimation tables. Consider the aluminum part below with a tolerance of  $\pm 1/64$ " for the two 0.50" radii and  $\pm 0.005$ " otherwise:




Figure A1: Rod support

### The process plan

The first step is to generate a process plan. Let's assume we begin with a stock size of 2.5"x2.25"x12" and that this will be manufactured in a job shop for very low quantities. We will use:

- A bandsaw to roughly cut the stock to size
- A manual vertical mill to create the planar features and the holes
- A belt sander to sand the radii (we can do this since the tolerance is not very high)

# Time Estimation Tables

The proposed time estimation method has the following sequence:

1. Begin with an engineering drawing
2. Develop a process plan
3. Estimate the times from simplified tables

The tables which follow are divided into three categories for each machine:

- Machine setup time
- Part fixturing time
- Material removal time

Machine setup time: Includes such things as cleaning up the machine from the last time it was used, loading tools and fixtures, and zeroing axes.

Part fixturing time: These times scale with weight (heavier parts take longer to load) and represent the time to pick up a part and secure it in place for the machining operation.

Material removal time:

It is important to note that the removal rates in the tables are for high speed steel (HSS) tooling.

- For sawing: removal rate is based on cross-sectional area of the cut
- For milling, turning, grinding, and sanding: removal rate is based on volume removed for roughing passes, and surface area finished for finish passes
- For drilling and tapping: plunge feed rate is based on the diameter and the depth of the hole

Also included in the tables are times for tool changes, time to index parts (in a part indexer), time to index tools (advance turret on a turret lathe), and programming times for CNC equipment.

The Appendices will help explain how to select machines and generate a process plan from a part drawing. Appendix A is a detailed time estimate of a "rod support". Additional useful data tables are given in Appendix B.

# Time estimation (minutes)

<b>Machine</b>	Operation (V = Volume, A = Area, P = Perimeter)	Fixture	Tool Change	Run (R=Rough, F=Finish)	Deburr/Inspect/ Measure
<b>Horizontal band saw</b>	Saw stock to ~4.125" A = 5.6525 in <sup>2</sup> , P = 9 in	0.23	-	2.02	0.30D, 0.05I
<b>Manual vertical mill</b>	Mill two ends to length 4" V = 0.703 in <sup>3</sup> A = 11.25 in <sup>2</sup> , P = 19in	0.20 0.20	2	0.13R 0.75F	0.63D, 0.05I, 0.13M
	Mill width to 2" V = 2.5 in <sup>3</sup> A = 10 in <sup>2</sup> , P = 13in	0.20	-	0.46R 0.67F	0.43D, 0.05I, 0.13M
	Mill out 2"X1.5"X4" V = 12 in <sup>3</sup> A = 14 in <sup>2</sup> , P = 15in	-	-	2.19R 0.93F	0.50D, 0.05I 0.13M, 0.13M
	Drill hole 1" diameter -Center drill -Pilot drill 1/2" -Pilot drill 63/64" -Ream	0.20	2 2 2 2	0.03 0.05 0.04 0.01	0.21D, 0.05I 0.17M
	Bore 1" radius V = 0.79 in <sup>3</sup> A = 1.57 in <sup>2</sup> , P = 7.28in	0.20	2	0.96R 0.01F	0.24D, 0.05I 0.06M
<b>Belt sender</b>	Sand 0.5 radii V = 0.05 in <sup>3</sup> A = 0.79 in <sup>2</sup> , P = 3.14in	0.08	-	0.20R 0.21F	0.10D, 0.05I 0.06M, 0.06M



# Summary Times (minutes)

Fixture	Tool Change	Run (R=Rough, F=Finish)	Deburr/Inspect/Measure
1.31	12	6.08	3.63

**Total Time 25.6 minutes**





Figure A1: Rod support



# Design for Machining

Design Rules for Machining  
From “Product Design for Manufacture and Assembly”  
by G. Boothroyd et al. (Dekker, 2002)

## *Standardization*

1. Utilize standard components as much as possible.
2. Pre-shape the workpiece, if appropriate, by casting, forging, welding, etc.
3. Utilize standard pre-shaped workpieces, if possible.
4. Employ standard machined features whenever possible.

## *Raw Material*

5. Choose raw materials that will result in minimum component cost (including cost of production and cost of raw material).
6. Utilize raw material in the standard forms supplied.

Handout on website


# Production Fixturing



**Vise**




**Soft jaws**



**T-slot & clamps on mill**




**"Tombstone"**




**With hydraulic clamping**

# Horizontal Milling Machine with Pallets



Pallet changer



Horizontal Mill with tombstone mounted on pallet


# Simplify set-up

- Have tools and fixtures available
- Identify Internal and External Setup
- Convert Internal to External Setup
- Streamlining all aspects of the setup operation

# Standardized Fixtures



# How would you make this part? Bill?




Pop quiz; how would you  
make a gun stock?



See video



Blanchard's  
Lathe  
built in 1822  
for the  
Springfield  
Armory





Blanchard's lathe, courtesy of the Springfield Armory National Historic Site.



# Fast Tool Server

<http://web.mit.edu/pmc/www/index.html>



# Molded Plastic and Composite Gun Stocks





# New Developments

- Diamond turning
- Hexapods
- Fast Tool Servers
- Cryogenic Machining

# New developments:



## Micro machines



Nano Corporation MTS1, MTS3, MTS5


	MTS2	MTS3	MTS4	MTS5
Footprint [mm <sup>2</sup> ]	100 x 150	200 x 300	220 x 320	260 x 324
Spindle drive P <sub>s</sub> [W]	11 DC	30 AC	30 AC	260 DC
Speed n <sub>max</sub> [min <sup>-1</sup> ]	10,000	3,000	3,000	20,000
Feed drive P <sub>r</sub> [W]	3 AC	30 AC	30 AC	30 AC

Source [NANO07]


Figure 3.14: Nano Corporation micro machines

Diamond turning  
And grinding of optical parts

# Hexapod Milling Machines



**Hexapod machining center  
(Ingersoll, USA)**



**Schematics**


# Institut für Werkzeugmaschinen und Fertigung Hexaglide from Zurich (ETH)



[www.iwf.mavt.ethz.ch/](http://www.iwf.mavt.ethz.ch/)




# Rotary Fast Tool Servo Machine for Eyeglass Lenses



D. Trumper & students

# Fast Tool Servo State of the Art




<i>Lorentz FTS</i>		<i>Piezoelectric FTS</i>			
1	Todd and Cuttino [19]	A	Kuuno [4]	F	Falter and Youden [10]
2	Weck [17]	B	Cuttino [13]	G	Dow [7]
3	Douglass [16]	C	Jared and Dow [9]	H	Weck [17]
4	Greene and Shinstock [18]	D	Rasmussen [5], [6]	I	Okazaki [12]
5	Ludwick and Trumper [20]	E	Patterson and Magrab [3]		




# Asymmetric Turning Operation


- Spectacle lenses
- Contact lenses
- Human lens implants
- Elements for laser vision correction surgery
- Camera lenses
- Image train elements in semiconductor processing
- Camshafts
- Not-round pistons



Tool at end of arm rotates about vertical axis




# Diamond Turning Machine Cross Section



# Cryogenic Machining

<http://www.youtube.com/watch?v=GFOXbb7P2jc>



# NC machine tool developed at MIT mid 1950's




FIG. 2.2. The MIT numerically controlled milling machine.




OXFORD SERIES ON ADVANCED MANUFACTURING 9

# NUMERICAL CONTROL

*Making a New Technology*

J. Francis Reintjes





# Environmental issues


- Waste material
- Energy
  - Machine, material (embodied energy), temperature controlled environment
- Lubricants and hydraulic fluids
- Cutting Fluids
  - Dry machining

# A Machine Tool Vs A SUV

The average power plant in the United States is 33% efficient.




Hawk TC-200






# 50% of the energy from the grid comes from coal


- electricity from the US grid comes with
  - 667 kg of CO<sub>2</sub>/MWh
  - 2.75 kg of SO<sub>2</sub>/MWh
  - 1.35 kg of NO<sub>x</sub>/MWh
  - 12.3 g Hg/GWh
  - etc.....



# annual SUV equivalents

## Comparison of SUVs to Machine Tools



 = 25 SUVs

# the fine print

- Assumptions:


Annual emissions resulting from the operation of a typical production machine tool

(22 kW spindle, cutting 57% of the time, 2 shifts, auxiliary equipment, electricity from US grid)

as measured in annual SUV equivalents (12,000 miles annually, 20.7 mpg)

- CO<sub>2</sub> – 61 SUV's
- SO<sub>2</sub> – 248 SUV's
- NO<sub>x</sub> – 34 SUV's

# Production machining energy Vs production rate



**Figure 3.3 Energy Use Breakdown by Type**

Ref. Toyota

# eye chart for energy values

	Production Maching Center (2000)		Automated Milling Machine (1998)		Automated Milling Machine (1988)		Manual Milling Machine (1985)	
<b>Electricity Breakdown</b>								
Constant start-up operations (idle)	85.2%		13.2%		27.0%		31.6%	
Run-time operations (positioning, loading, etc)	3.5%		20.2%		24.9%		0% (manual)	
Material removal operations (in cut)	11.3%		65.8%		48.1%		69.4%	
<b>Electricity Requirements</b>								
Constant start-up operations (idle)	166 kW		1.2 kW		3.4 kW		0.7 kW	
Run-time operations (positioning, loading, etc)	6.8 kW		1.8 kW		3.1 kW		0 kW	
Material removal operations (in cut)	22 kW		5.8 kW		6.0 kW		2.1 kW	
<b>Machine Use Scenario</b>								
Arbitrary Number of work hours	1000 hours		1000 hours		1000 hours		1000 hours	
Machine uptime	90%		90%		90%		90%	
Machine hours (idle, positioning, or in cut)	900 hours		900 hours		900 hours		900 hours	
Percentage of machine hours spent idle	10%		35%		35%		65%	
Machine hours spent idle	90 hours		315 hours		315 hours		585 hours	
Active machine hours per 1000 work hours	810 hours		585 hours		585 hours		315 hours	
<b>Machining Scenario</b>								
Percentage of machine hours spent positioning	30%		60%		60%		70%	
Machine hours spent positioning	243 hours		351 hours		351 hours		221 hours	
Percentage of machine hours spent in cut	70%		40%		40%		30%	
Machine hours spent in cut	567 hours		234 hours		234 hours		94.5 hours	
<b>Electricity Use per 1000 work hours</b>								
Constant start-up operations (idle)	149288 kWh		1038 kWh		3033 kWh		600 kWh	
Run-time operations (positioning, loading, etc)	5471 kWh		1033 kWh		1818 kWh		0 kWh	
Material removal operations (in cut)	6237 kWh		673 kWh		702 kWh		100 kWh	
Total electricity use per 1000 work hours	160996 kWh		2744 kWh		5553 kWh		700 kWh	
<b>Electricity Used per Material Removed</b>								
Material Machined	Aluminum	Steel	Aluminum	Steel	Aluminum	Steel	Aluminum	Steel
Material Removal Rate	20.0 cm <sup>3</sup> /sec	4.7 cm <sup>3</sup> /sec	5.0 cm <sup>3</sup> /sec	1.2 cm <sup>3</sup> /sec	5.0 cm <sup>3</sup> /sec	1.2 cm <sup>3</sup> /sec	1.5 cm <sup>3</sup> /sec	0.35 cm <sup>3</sup> /sec
Material removed per 1000 work hours	40824000 cm <sup>3</sup>	9593640 cm <sup>3</sup>	4212000 cm <sup>3</sup>	1010880 cm <sup>3</sup>	4212000 cm <sup>3</sup>	1010880 cm <sup>3</sup>	510300 cm <sup>3</sup>	119070 cm <sup>3</sup>
Electricity used/Material removed	14.2 kJ/cm <sup>3</sup>	60 kJ/cm <sup>3</sup>	2.3 kJ/cm <sup>3</sup>	10 kJ/cm <sup>3</sup>	4.7 kJ/cm <sup>3</sup>	20 kJ/cm <sup>3</sup>	4.9 kJ/cm <sup>3</sup>	21 kJ/cm <sup>3</sup>


# Results are in terms of primary energy

	Production Machining Center (2000)		Manual Milling Machine (1985)	
<b>Electricity Breakdown</b>				
Constant start-up operations (idle)	85.2%		31.6%	
Run-time operations (positioning, loading, etc)	3.5%		0% (manual)	
Material removal operations (in cut)	11.3%		69.4%	
<b>Electricity Requirements</b>				
Constant start-up operations (idle)	166 kW		0.7 kW	
Run-time operations (positioning, loading, etc)	6.8 kW		0 kW	
Material removal operations (in cut)	22 kW		2.1 kW	
<b>Machine Use Scenario</b>				
Arbitrary Number of work hours	1000 hours		1000 hours	
Machine uptime	90%		90%	
Machine hours (idle, positioning, or in cut)	900 hours		900 hours	
Percentage of machine hours spent idle	10%		65%	
Machine hours spent idle	90 hours		585 hours	
Active machine hours per 1000 work hours	810 hours		315 hours	
<b>Machining Scenario</b>				
Percentage of machine hours spent positioning	30%		70%	
Machine hours spent positioning	243 hours		221 hours	
Percentage of machine hours spent in cut	70%		30%	
Machine hours spent in cut	567 hours		94.5 hours	
<b>Electricity Use per 1000 work hours</b>				
Constant start-up operations (idle)	149288 kWh		600 kWh	
Run-time operations (positioning, loading, etc)	5471 kWh		0 kWh	
Material removal operations (in cut)	6237 kWh		100 kWh	
Total electricity use per 1000 work hours	160996 kWh		700 kWh	
<b>Electricity Used per Material Removed</b>				
Material Machined	Aluminum	Steel	Aluminum	Steel
Material Removal Rate	20.0 cm <sup>3</sup> /sec	4.7 cm <sup>3</sup> /sec	1.5 cm <sup>3</sup> /sec	0.35 cm <sup>3</sup> /sec
Material removed per 1000 work hours	40824000 cm <sup>3</sup>	9593640 cm <sup>3</sup>	510300 cm <sup>3</sup>	119070 cm <sup>3</sup>
<b>Electricity used/Material removed</b>	<b>14.2 kJ/cm<sup>3</sup></b>	<b>60 kJ/cm<sup>3</sup></b>	<b>4.9 kJ/cm<sup>3</sup></b>	<b>21 kJ/cm<sup>3</sup></b>

**Table 8** Typical Energy Costs of Common Materials (MJ/kg)

Material	Energy cost	Made or extracted from
Aluminum	227–342	Bauxite
Bricks	2–5	Clay
Cement	5–9	Clay and limestone
Copper	60–125	Sulfide ore
Glass	18–35	Sand, etc.
Iron	20–25	Iron ore
Limestone	0.07–0.1	Sedimentary rock
Nickel	230–70	Ore concentrate
Paper	25–50	Standing timber
Polyethylene	87–115	Crude oil
Polystyrene	62–108	Crude oil
Polyvinylchloride	85–107	Crude oil
Sand	0.08–0.1	Riverbed
Silicon	230–235	Silica
Steel	20–50	Iron
Sulfuric acid	2–3	Sulfur
Titanium	900–940	Ore concentrate
Water	0.001–0.01	Streams, reservoirs
Wood	3–7	Standing timber

Ref Smil



**FIGURE 6.8** A bar chart of the embodied energies of materials per unit mass.



# Sample calculation

- 1 kg part made from 2 kg of aluminum stock 2024
- **production machining** 14.2 kJ/cm<sup>3</sup>
- 1000 g /2.7 g/cm<sup>3</sup> = 370 cm<sup>3</sup>  
(14.2 X 370 = 5.25 MJ) X 3 = **15.8 MJ**
- **material production**  
(284.5 MJ/kg X 2 kg = **569 MJ**)+15.8 =  
**585 MJ/ kg of part**

# Power plant efficiency

## Box 3.1

### Efficiency of a power station

For a typical coal-fired power station, the steam reaches about  $500^{\circ}\text{C} = 773\text{ K}$ : this is  $T_h$ . The cold temperature,  $T_c$ , is not less than ambient temperature: it can be taken as  $300\text{ K}$  ( $27^{\circ}\text{C}$ ). Carnot efficiency is given by Equation (3.13):

$$\begin{aligned}\eta &= 1 - 300/773 \\ &= 0.61\end{aligned}$$

This is the theoretical limit, and once other losses are accounted for, most power stations end up with overall efficiency around 35 per cent. The remaining energy is lost as low grade heat and is generally dissipated by cooling towers, or into a lake, river or the sea.

For a nuclear station, temperatures are cooler, to restrict corrosion for safety reasons. At  $T_h = 300^{\circ}\text{C} = 573\text{ K}$ , the Carnot efficiency will be:

$$\begin{aligned}\eta &= 1 - 300/573 \\ &= 0.52\end{aligned}$$

Again there are heat losses elsewhere, giving overall efficiency of 25–30 per cent. Thus the waste heat of 65–75 per cent of heat input contains between two and three times as much energy as the electricity produced.

# emissions for the power station

- 585 MJ of primary energy (195 MJ of electricity / efficiency = .33), or .06 MWh. This gives:
  - 33.35 kg of CO<sub>2</sub>
  - 140 g of SO<sub>2</sub>
  - 0.6 g of Hgall for a 1 kg part