



# How We Machined Boxy

Fred Proctor, NIST

ISO TC 184 SC 4

STEP Manufacturing Team Meeting

June 16-18, 2010


NIST, Gaithersburg MD USA





# The Process

- We started with the 8-setup STEP-NC file with the accompanying 3D PDF that showed the setup assumptions
- We preferred a 7-setup process plan and got one
- We found we needed more information on setup and tooling from the STEP-NC data and got it
- We cut parts in wax and steel and found we had to adjust speeds and feeds to suit our setup
- We looked into cutting forces and spindle power




Dimensions look like a cube of dimensions 85 mm X 85 mm X 82.5 mm.

How can we see the actual stock size in the STEP-NC data?

default workpiece

- Machine Group-1
  - Setup 1 Machining D
    - OP 1 Face Millin
      - Alterna
      - Alterna
      - Alterna
      - Alterna
      - Alterna
      - Alterna
    - Setup 2 Machining D
    - Setup 3 Machining D
    - Setup 4 Machining o
    - Setup 5 Machining o
    - Setup 6 Machining D
    - Setup 7 Machining o
    - Setup 8 Machining D

- Enable/Disable Items
- Show NC Functions
- Import
- Optimize Feeds ...
- Insert NC Function ...
- Insert Workplan
- Change to Selective
- Edit Name ...
- Edit STRL ...
- Edit Setup Placement ...
- Add Faces to All Workingsteps
- Workpiece Properties ...**
- Machine Parameters ...



**Workpiece Properties**

Stock

Name Boxy\_Part\_Rawpiece

Material

Explicit Geometric Shape

Length (x) = 85.0 mm

Width (y) = 85.0 mm

Height (z) = 85.0 mm

Workpiece

Name Boxy\_Part\_

Material

Explicit Geometric Shape

Length (x) = 85.0 mm


Width (y) = 85.0 mm




Height (z) = 82.5 mm

OK

Cancel

**Here we see the assumed stock size nicely.**







Likewise, we can see the Z coordinate of the top of the part is 2.5 mm.

But the machinist typically wants to set the coordinates of faces that will be placed against locating stops, such as a parallel at the vise bottom, the vise back and a stop at the right face. These preferences vary by machinist.

In our case, we want the right face, back face and bottom face to be (0, 0, 0) in XYZ, respectively.

Workplans Part Properties Tools Features  
Selected Face #66491 at (18.0025, 28.3771, 2.5)







**An outside expert preferred to center the part in the vise during machine to evenly distribute clamping forces, and use the machine's perpendicularity to square up the part rather than using a machinist's square.**

**We wanted to rework the data to include an initial setup in which three orthogonal surfaces were milled.**






**Process planning expert Magnus graciously prepared a new data set for us, a seven-setup sequence in which the first setup is used to lightly mill three perpendicular reference surfaces. These are then placed against our locating surfaces on the vise for the next setup. Subsequent machined faces can then be used the same way.**





# Tool Requirements

- But we need to know what flexibility we have in choosing tools.
  - Do we need exactly a 57.7 mm cutting length?
  - Can it be shorter? How much shorter?
  - Can it be a bit narrower? Will 12.5 mm be OK?
- This brought up the subject of tool requirements that we will be discussing later in this meeting.



```
SCHEMA tool_requirements_schema;  
  
TYPE prescription_type = ENUMERATION OF (  
    required_to_prevent_collision,  
    required_to_remove_material,  
    required_by_customer,  
    recommended_to_minimize_deflection,  
    recommended_to_minimize_vibration,  
    recommended_from_best_practices,  
    recommended_from_testing  
);  
END_TYPE;
```



# What we would do differently

- We would do this part in six setups
  - the first of seven setups was clamped high to allow for the machining of large reference surfaces on the right and back sides
  - since it was clamped high, we chose not to do pocketing operations that might pop the part out
  - we really only need small reference surfaces, so we can clamp more fully in the first setup and finish up all the operations at once
- We would do spiral entry cuts for the pockets, using a face-cutting end mill for clean cutting




# What we want added

- We generate NC code at the end, since our Siemens 840D doesn't support STEP-NC natively
- The machinist looks at the NC code during operation for reminders about what to do
- Reminders, via comments, should include:
  - how the part is to be oriented
  - what reference surfaces should be used and at what coordinate values
  - what tool is being used and the chip loading
  - what operation will be done
  - how long this will take



**Ideally, the STEP-NC process plan should come out of the CAM system with all the information the machinist needs to set up and machine the part.**

**No sticky notes required!**



Remember to use that special tool we talked about!