Predator CNC Editor™ - KBA #2200002

Knowledge Base Article for improving CNC editing

Issue

Receive from CNC does not work under Windows 98

Solution

Predator CNC Editor v6.0.159 contained a bug that prevents Receive from CNC to work under certain flavors of Windows 98. An update to v6.0.198 or newer does fix this problem.

More Information

Some version of Windows 98 such as W98SE do work as well as all versions of Windows NT, ME, 2000 and XP.

NOTE: This bug is not present in v5.x or in v6.1 of the Predator CNC Editor.

References

Should additional details be required, contact Predator Software via the following:

support@predator-software.com

The information in this article applies to:

- Predator CNC Editor v6.0.159

© 1994 – 2004 Predator Software Inc. All rights reserved.

THIS IS A LIVING DOCUMENT. The information contained in this document represents the current view of Predator Software Inc. on the issues discussed as of the date of publication. Because Predator Software Inc. must respond to changing market conditions, it should not be interpreted to be a commitment on the part of Predator Software Inc., and Predator Software Inc. cannot guarantee the accuracy of any information presented after the date of publication.

Last Reviewed: 09/28/04