



Nome usuario
Admin
26.11.2018 14:47

Número de relatório (0)
Nome peça
Part_AM

Numero da O.P

INSPETORES

CLIENTE

TURNOS

El. No.	Line No	Element	Pnt. Ref.	X-Coord. Nominal	Y-Coord. Y-Angle Up/Lo	Z-Coord. Z-Angle Actual	Diameter Dist./Ang. Dev./Error	Variance mm
1	21	d_y1		70.000	0.250	69.853	-0.147	
		Distancia XY			-0.250			--****-----
2	23	d_y2		70.000	0.250	69.841	-0.159	
		Distancia XY			-0.250			--****-----
3	25	d_x1		50.000	0.250	49.771	-0.229	
		Distancia XY			-0.250			*****-----
4	27	d_x2		50.000	0.250	49.766	-0.234	
		Distancia XY			-0.250			*****-----
5	41	dy_c1		7.500	0.250	7.468	-0.032	
		Distancia XY			-0.250			----**-----
6	43	dy_c2		7.500	0.250	7.457	-0.043	
		Distancia XY			-0.250			----**-----
7	45	dx_c1		7.500	0.250	7.388	-0.112	
		Distancia XY			-0.250			---***-----
8	47	d_c1_c2		35.000	0.250	34.851	-0.149	
		Distancia XY			-0.250			--****-----
9	49	dy_c1_c3		55.000	0.250	54.972	-0.028	
		Distancia XY			-0.250			----**-----